

Message Text

LIMITED OFFICIAL USE

PAGE 01 NIAMEY 02751 150759Z

10

ACTION FBO-05

INFO OCT-01 AF-06 ISO-00 A-01 OC-05 CCO-00 /018 W

----- 056561

P R 141453Z JUL 75

FM AMEMBASSY NIAMEY

TO SECSTATE WASHDC PRIORITY 1196

INFO AMEMBASSY ACCRA

LIMITED OFFICIAL USE NIAMEY 2751

E.O. 11652: N/A

TAGS: ABLD, NG

SUBJ: ROOF REHABILITATION, OB PROPERTY 01559-B

FOR A/FBO AND O/C NAEHER

REF: A. STATE 163552 B. NIAMEY 2632 C. NIAMEY 2533

1. WHILE WE APPRECIATE EFFORTS UNDER WAY TO SOLVE CHANCERY ROOFING PROBLEMS AS OUTLINED REF A, WE ARE CONCERNED OVER DELAYS POSED BY OPTIONS BEING CONSIDERED. WE ARE NOW IN PEAK OF RAINY SEASON AND HAPPILY FOR THIS RECENTLY DROUGHT STRICKEN COUNTRY, RAINS AROUND NIAMEY SEEM ABUNDANT THIS SUMMER. HOWEVER, ADVENT OF RAIN POSING SOME CRITICALLY URGENT PROBLEMS WHICH REQUIRE REMEDIAL ACTION SOONEST. AS REPORTED NIAMEY 2533, SOME OF ROOF LEAKS ARE OVER C&R UNIT. RAIN ACCUMULATES ON ROOF AND THEN SEEPS THROGH, DRIPPING OVER COMMUNICATIONS EQUIPMENT ON TO FLOOR. AFTER LAST RAIN WE HAD THREE BUCKETS COLLECTING THIS SEEPAGE.

2. THIS POSES FIRE HAZARD AS WELL AS SERIOUS THREAT TO PERSONNEL AND COMMUNICATIONS EQUIPMENT. ANTENNA COUPLER ON FLOOR GENERATES 10,000 VOLTS AND MUST BE PROTECTED FROM ELEMENTS.

3. WHATEVER DECISION REACHED ABOUT REPAIRS ON REST
LIMITED OFFICIAL USE

LIMITED OFFICIAL USE

PAGE 02 NIAMEY 02751 150759Z

OF CHANCERY ROOF, URGE IMMEDIATE ACTION ON REPAIRING

LEAKS OVER C&R UNIT.HECK

LIMITED OFFICIAL USE

NNN

Message Attributes

Automatic Decaptioning: X
Capture Date: 01 JAN 1994
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: n/a
Control Number: n/a
Copy: SINGLE
Draft Date: 14 JUL 1975
Decaption Date: 01 JAN 1960
Decaption Note:
Disposition Action: RELEASED
Disposition Approved on Date:
Disposition Authority: CunninFX
Disposition Case Number: n/a
Disposition Comment: 25 YEAR REVIEW
Disposition Date: 28 MAY 2004
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1975NIAMEY02751
Document Source: CORE
Document Unique ID: 00
Drafter: n/a
Enclosure: n/a
Executive Order: N/A
Errors: N/A
Film Number: D750243-0840
From: NIAMEY
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1975/newtext/t19750758/aaaacaib.tel
Line Count: 62
Locator: TEXT ON-LINE, ON MICROFILM
Office: ACTION FBO
Original Classification: LIMITED OFFICIAL USE
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 2
Previous Channel Indicators: n/a
Previous Classification: LIMITED OFFICIAL USE
Previous Handling Restrictions: n/a
Reference: 75 STATE 163552, 75 NIAMEY 2632, 75 NIAMEY 2533
Review Action: RELEASED, APPROVED
Review Authority: CunninFX
Review Comment: n/a
Review Content Flags:
Review Date: 26 AUG 2003
Review Event:
Review Exemptions: n/a
Review History: RELEASED <26 AUG 2003 by BoyleJA>; APPROVED <10 DEC 2003 by CunninFX>
Review Markings:

Margaret P. Grafeld
Declassified/Released
US Department of State
EO Systematic Review
06 JUL 2006

Review Media Identifier:
Review Referrals: n/a
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
Secure: OPEN
Status: NATIVE
Subject: ROOF REHABILITATION, OB PROPERTY 01559-B FOR A/FBO AND O/C NAEHER
TAGS: ABLD, NG
To: STATE
Type: TE
Markings: Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 06 JUL 2006